

## PRODUCT UPGRADE NOTIFICATION: SILO JUNCTION BOX

### Notification

Munters **SILO JUNCTION BOX-RJB4** will be discontinued, due to its replacement by a redesigned improved Munters **SILO JUNCTION BOX**.

#### **SILO JUNCTION BOX-RJB4**

The last shipment date: 30.04.2022

The spare parts last shipment date: 31.04.2027

#### **SILO JUNCTION BOX**

Availability: 01.05.2022

The redesigned solution "**SILO JUNCTION BOX**" supports connectivity to 6 x load cells and is housed in a convenient, space efficient, easy to install aluminum IP67 enclosure.

Later in 2022, a version with pluggable connectors will be introduced. That will significantly improve troubleshooting and maintenance process.

### Discontinued Products

- 911-02-10001 SILO JUNCTION BOX-RJB4-POU-MUR
- 911-02-20001 SILO JUNCTION BOX-RJB4-POU-NRO



### New Replacement Product

- 911-02-10002 SILO JUNCTION BOX-POU



### Spare Parts

- |                |                        |                       |
|----------------|------------------------|-----------------------|
| • 911-99-00006 | RJB4 CARD -POU- (RJB4) | Discontinued Version  |
| • 911-99-000xx | SILO JUNCTION CARD     | New Replacing Version |

**Munters Israel**

18 Hasivim st. , Petach Tikva 4959376, Israel / Phone: +972 3 920 6200 / Fax: +972 3 924 9834  
info@munters.co.il / [www.munters.com](http://www.munters.com)